

ENGINEERING CHANGE NOTICE

DART AEROSPACE LTD

Date: 11.02.03	Job No.:	ADR Yes/No: NO	ADR Date:	ECN #: 11- 516
Product No.: D412-791		Created By: KB	Approved By:	
Product Name: Safety Enhancement Kits		Checked By: DS	General Manager Approval: NA	

Distribution	Reqd	Resp	Initial / Date
Production Manager / Coord.	Y	LL	LL 11-02-03
Purchasing Coord.	N		
Production Engineering Coord.	N		

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord.	N		
QC Coordinator	N		
Customer Technical Support	Y	MB	MB 11.02.03
Marketing	Y	SW	SW 11.02.07
Customer Order Processing	N		

Reason for Change:
Customer Feedback - Un-annuciated pitot heat failure.

Documents Affected:

MDL-D412-791 Rev. C
D412-791-907 Rev. C
SB11-1 Rev. A

PARTS MUST COMPLY ☐ PREVIOUS PARTS SATISFACTORY ☒

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	Y	SW	Send copy of SB11-1 / D412-791-907 Rev. C	SW 11.04.06
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Master Document List (MDL)	Y	KB	MDL-D412-791 Rev. C	11.01.11
6	Update Product Compatibility Matrix	N			
7	Create Eurocopter Form (FEE)	N			
8	Notify TC / FAA of Change	N			
9					

#	Document Control Actions	Reqd	Resp	Notes	Complete
10	Move Electronic Files	Y	KJ	Electronic files in KB's Kim Folder	11.02.07
11	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ		11.02.07
12	Update Approved/Preliminary PDF Files	N	KB		11.02.07
13	Update Document Record (DR)	Y	KB	DR-D412-791 Rev. B	11.02.03
14	Update Product Development Summary	N			
15	Update QSI 021 and/or STC Approval List	N			
16	Update Parts / STC Database	N			
17	Update / Verify ARC Database	N			
18	Create / Update Change Record Form / Item Card Database	N			
19	Create / Update PPP's	N			
20	Update Document Control Database / Laminated Dwgs	N			
21	Update Grey Project / Electronic Binder PDF Files	Y	KJ	Binder and CD shipped to Hawkesbury	11.02.07
22	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		11.02.07
23					
24					

Description / Action:

SB11-1 and D412-791-907 to be released to correct a wiring problem that could possibly lead to a un-annuciated pitot heat failure.
Send a copy of SB11-1 to all customers who have purchased D412-791-047.

ECN Verified & Complete:

Date: 11/04/11